

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	0	screw & bore & bioabsorbable adj material & removable adj driver	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 09:34
2	BRS	L2	0	screw & bioabsorbable adj material & removable adj driver & bore	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 09:35
3	BRS	L3	184	screw & bioabsorbable adj material & bore	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 09:58

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	0	bioabsorbable adj bone adj screw & heated adj driver	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 10:48
2	BRS	L2	0	bioabsorbable adj bone adj screw & shrink adj fit & driver	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 10:50
3	BRS	L3	74	screw & shrink adj fit & driver	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 12:25
4	BRS	L4	0	screw & shrink adj fit adj driver	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 11:18

	Type	L #	Hits	Search Text	DBs	Time Stamp
5	BRS	L5	1	screw adj bore & shrink adj fit & driver	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 11:20
6	BRS	L6	36	screw adj bore & heat & driver	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 12:38
7	BRS	L7	0	medical adj screw adj bore & driver & heat adj shrink	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 11:34
8	BRS	L8	130	screw & (shrink\$4 or shrunk) & bone & tool & bore	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 12:28

	Type	L #	Hits	Search Text	DBs	Time Stamp
9	BRS	L9	110	8 & fit	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 12:29
10	BRS	L10	3	8 & shrink\$fit	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 12:29
11	BRS	L11	9162	screw & bore & heat\$3 & tool	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 12:39
12	BRS	L12	42	11 & shrink\$fit	USPAT; US-PG PUB; EPO; JPO; DERVENT; IBM_TDB	2003/10/14 12:41

	Type	L #	Hits	Search Text	DBs	Time Stamp
13	BRS	L13	41	12 & mat\$5	USPAT; US - PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 12:45
14	BRS	L14	36	13 & remov\$3	USPAT; US - PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 12:54

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	IS&R	L1	0	("tool&non\$threadedadje xternaladjcylindricaladj jsurface&screwadj (boreo rcanula)".PN.	USPAT	2003/10/1 4 14:03
2	BRS	L2	0	tool & non\$threaded adj external adj cylindrical adj surface & screw adj (bore or canula)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:05
3	BRS	L3	0	tool & non\$threaded adj external adj surface & screw & non\$circular adj axial adj through\$bore	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:07
4	BRS	L4	0	bone adj fixation adj screw & shrink\$fit & (tool or driver)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:09
5	BRS	L5	0	bone adj screw & shrink\$fit & (tool or driver)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:10

	Type	L #	Hits	Search Text	DBs	Time Stamp
6	BRS	L6	72	bore & screw & shrink\$fit & (tool or driver)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:11
7	BRS	L7	6	6 & remov\$4 adj tool	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:21
8	BRS	L8	7	6 & remov\$4 adj (tool or driver)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:22

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	IS&R	L1	0	("tool&non\$threadedadje xternaladjcylindricaladj jsurface&screwadj (bore rcanula)".PN.	USPAT	2003/10/1 4 14:03
2	BRS	L2	0	tool & non\$threaded adj external adj cylindrical adj surface & screw adj (bore or canula)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:05
3	BRS	L3	0	tool & non\$threaded adj external adj surface & screw & non\$circular adj axial adj through\$bore	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:07
4	BRS	L4	0	bone adj fixation adj screw & shrink\$fit & (tool or driver)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:09
5	BRS	L5	0	bone adj screw & shrink\$fit & (tool or driver)	USPAT; US-PG; PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:10

	Type	L #	Hits	Search Text	DBs	Time Stamp
6	BRS	L6	72	bore & screw & shrink\$fit & (tool or driver)	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:11
7	BRS	L7	6	6 & remov\$4 adj tool	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:21
8	BRS	L8	7	6 & remov\$4 adj (tool or driver)	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:38
9	BRS	L9	2	shrink\$fit adj chuck & remov\$4 adj (tool or driver)	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:39

	Type	L #	Hits	Search Text	DBs	Time Stamp
10	BRS	L10	0	shrink\$fit adj screw & remov\$4 adj (tool or driver)	USPAT; US-PG PUB; EPO; JPO; DERWE NT; IBM_T DB	2003/10/1 4 14:52